## **PTA Security Advisory-No: 47**

05 April 2019

Threat Classification: Security Vulnerability

Name: Signature verification bypass vulnerability (CVE-2019-5300)

**Source:** Affect following products of Huawei:

• Huawei Enterprise Router / Firewall

**Distribution**: The vulnerabilities can be exploited in the following products of <u>Huawei</u>:

Product Name	Affected Version	Updated Version to Fix Vulnerability
Huawei AR1200 Series Huawei AR1200-S Series Huawei AR150 Series Huawei AR160 Series Huawei AR2200 Series Huawei AR2200 Series Huawei AR2200-S Series Huawei AR3200 Series Huawei SRG1300 Series Huawei SRG3300 Series Huawei SRG3300 Series	V200R007C00 V200R008C20 V200R008C50	V200R010SPH003
	V200R009C00 V200R010C00	
	V200R008C20 V200R008C50	
	V200R009C00 V200R010C00	

**Exploited Vulnerabilities:** Hackers with high privileges may exploit the vulnerability exists in Huawei products to bypass integrity checks for software images and install a malicious software image on the affected device. On the successfully exploit, the attacker could bypass integrity checks for software images and install the malicious software images on the affected device.

## **Recommendations:**

- Update following official firmware/image to fix the aforementioned vulnerabilities:
  - o <a href="https://support.huawei.com/enterprise/en/software/index.html">https://support.huawei.com/enterprise/en/software/index.html</a>
- Whenever required, run software with minimal access rights and privileges.
- Use licensed antivirus and regularly obtain its latest updates with its real-time scanning capabilities enabled.
- Only use licensed software and avoids download/use of crack and pirated software.
- Designate PoC from your security / network team (if yet not designated), for seeking assistance and reporting security issues.
- In case of any incident, please report to this office.